

# MACHINERY'S REFERENCE SERIES

EACH NUMBER IS A UNIT IN A SERIES ON ELECTRICAL AND  
STEAM ENGINEERING DRAWING AND MACHINE  
DESIGN AND SHOP PRACTICE

NUMBER 100

## AUTOMATIC SCREW MACHINE PRACTICE

PART II

DESIGNING AND CUTTING CAMS FOR  
BROWN & SHARPE AUTOMATIC  
SCREW MACHINES

By DOUGLAS T. HAMILTON

### CONTENTS

Designing Screw Machine Cams	- - - - -	3
Cams for Screw Slotting Attachments	- - - - -	22


### APPENDIX

Milling Screw Machine Cams, by WILLIAM W. JOHNSON	32
---	----



113  
1100

Automatic Screw Machine Practice for the Brown & Sharpe automatic screw machines is covered in eight Reference Books, Nos. 99 to 106, inclusive. Reference Book No. 99, "Operation of the Brown & Sharpe Automatic Screw Machines," deals with the construction of these machines and the setting-up of the tools. No. 100, "Designing and Cutting Cams for Automatic Screw Machines," gives detailed instruction on cam design, and describes a simplified method for milling cams. No. 101, "Circular Form and Cut-off Tools for the Automatic Screw Machine," deals with the general arrangement and the calculations of these tools, and describes the different methods employed in their making. No. 102, "External Cutting Tools for the Automatic Screw Machine," deals with the design and construction of box-tools, taper turning tools, hollow mills, and shaving tools. No. 103, "Internal Cutting Tools for the Automatic Screw Machine," deals with centering tools, cross-slide drilling attachments, counterbores, reamers, and recessing tools. No. 104, "Threading Operations on the Automatic Screw Machine," treats on cam design for threading operations, threading dies, taps and tap drills, die and tap holders, and thread rolling. No. 105, "Knurling Operations on the Automatic Screw Machine," describes the construction of knurling holders, and gives directions for the making of knurls and the design of tools and cams used in connection with knurling operations. No. 106, "Milling, Cross-drilling and Burring Operations on the Automatic Screw Machine," describes screw-slotting attachments, index drilling attachments, and burring attachments, giving directions for their use and for the design of cams for them.



## CHAPTER I

### DESIGNING SCREW MACHINE CAMS

The object of the present chapter is to give the average mechanic and draftsman a clear idea of the methods employed when designing special tools and cams for the Brown & Sharpe automatic screw machine. The first thing to be explained is the change-gear mechanism, as on this are based the fundamental principles used in the construction of the tables for laying out cams. Following this, the construction of the rise and drop on the cams, which is governed by the amount of clearance necessary for one tool to pass another will be treated. Then




Fig. 1. Diagram of Gearing on the No. 00 Brown & Sharpe Automatic Screw Machine

a number of general points which should be of value especially to those who are not experienced in this class of work, are given.

#### Change-gear Mechanism

A system of simple gearing is used on the No. 00 Brown & Sharpe automatic screw machine, as clearly shown in Fig. 1. The worm has a double thread; hence for every revolution of the worm, the worm-wheel travels through a distance of two teeth. To find the change gears, assume that it is required to make one piece in 12 seconds. This necessitates that the worm-wheel make one revolution in 12 seconds. As there are 40 teeth in the worm-wheel and the worm has a double thread, the worm shaft will make  $40 \div 2$  or 20 revolutions in 12 seconds. The

driving shaft runs constantly at 120 R. P. M. or 2 revolutions per second. Then the driving shaft will make  $12 \times 2$  or 24 revolutions in 12 seconds. As, in this case, the driving shaft is required to run the faster, we will put the gear with the smaller number of teeth on that shaft. Now if we have gears having 20 and 24 teeth, respectively, they will "do the trick," but after referring to the gears supplied with the machine we find that a gear with 24 teeth is not available, so multiplying the number of teeth in each by two (which does not change the ratio) the gears will be: 40-tooth gear on driving shaft; 48-tooth gear on worm shaft.

On the No. 0 Brown & Sharpe automatic screw machine there is also one driving and one driven gear, but on this machine the gear




Fig. 2. Diagram of Gearing on the No. 0 Brown & Sharpe Automatic Screw Machine

which is called the driver is placed on the second driving shaft as shown in Fig. 2. Then, before finding the change gears it is necessary to find the speed of the gear on this second driving shaft. The first driving shaft runs constantly at a speed of 180 R. P. M. Then the

speed of the second driving shaft =  $\frac{180 \times 58}{87} = 120$  R. P. M. To find

the change gears, assume that it is required to make one piece in 36 seconds. (To obviate confusion, we will call the second driving shaft, which runs at 120 R. P. M., the main driving shaft). Since the cam shaft is to make one revolution in 36 seconds and as there are 60 teeth in the worm-wheel and the worm has a single thread, the worm shaft will make 60 revolutions in 36 seconds. The driving shaft which runs at 120 R. P. M., or two revolutions per second, will make 72 revolutions in 36 seconds. From this we see that the driving shaft is required to run the faster of the two, and, hence, the smaller gear

will be put on this shaft. The gears to use could have 60 and 72 teeth, respectively; or, by dividing the number of teeth in each by two, we have 30 and 36 teeth, respectively.

The gears can also be found directly by the formula:

$$\frac{120 \times D}{W} = \frac{3600}{S} \quad (1)$$

where  $D$  = number of teeth in gear on driving shaft,

$W$  = number of teeth in gear on worm shaft,

$S$  = time in seconds to make one piece.

Then,  $\frac{120 \times D}{W} = \frac{3600}{36}$  or  $120 D = 100 W$ ;  $W = 1.2 D$ .

Let  $D = 30$ . Then  $W = 30 \times 1.2 = 36$ .




Fig. 3. Diagram of Gearing on the No. 2 Brown & Sharpe Automatic Screw Machine

A system of compound gearing is used on the No. 2 Brown & Sharpe automatic screw machine making it necessary to find the various gears by factoring. To explain the method of finding the gears we will take a practical example. Let it be required to find the gears to make one piece in 28 seconds. Referring to Fig. 3 we find that the speed of the driving shaft is 120 R. P. M. There are 60 teeth in the worm-wheel and the driving worm has a single thread. Thus the cam shaft must make one revolution in 28 seconds. The worm shaft will make 60 revolutions in 28 seconds as the worm has a single thread. The driving shaft makes 2 revolutions per second or 56 revolutions in 28 seconds. It will thus be seen that the worm shaft (or driven shaft) is required to run the faster of the two. Therefore, the product of

the number of teeth in the driven gears should be smaller than the product of the number of teeth in the driving gears. The ratio of the gearing equals  $\frac{60}{56}$ . By dividing the numerator and denominator into

factors and multiplying each pair of factors by the same number we find the gears:

$$\frac{60}{56} = \frac{10 \times 6}{4 \times 14} = \frac{(10 \times 8) \times (6 \times 6)}{(4 \times 8) \times (14 \times 6)} = \frac{80 \times 36}{32 \times 84}$$

Then the gears are as follows:

80, gear on driving shaft; 36, second gear on stud; 32, first gear on stud; 84, gear on worm shaft.

#### How Tables for Laying out Cams are Constructed

Before a table can be constructed it is necessary to know the range of spindle speeds obtainable and also the speed of the driving shaft. Then the number of seconds to make one piece is placed in the first column of the table, and the number of revolutions to complete one piece is placed under the various spindle speeds as shown in Table I. The total number of revolutions to make one piece is found by the

following formula:  $r = \frac{R \times S}{60}$ , where  $R$  = revolutions of spindle per

minute (R. P. M.),  $S$  = time in seconds to make one piece, and  $r$  = total number of revolutions to make one piece. The total number of revolutions to complete one piece can also be found by adding together the number of revolutions required for each operation plus the revolutions required for clearance, feeding the stock, and revolving the turret. The number of seconds to make one piece is found by the following formula:

$$S = \frac{r \times 60}{R} \quad (2)$$

The time required to feed stock and revolve the turret on the various Brown & Sharpe automatic screw machines is as follows: No. 2 machine, 1 second; No. 0 machine,  $\frac{2}{3}$  seconds; No. 00 machine,  $\frac{1}{2}$  second. The revolutions of the spindle required to feed stock and revolve the turret on the various machines are found by the following formulas:

$$\text{No. 2 machine, } r_1 = R \div 60 \quad (3)$$

$$\text{No. 0 machine, } r_1 = R \div 90 \quad (4)$$

$$\text{No. 00 machine, } r_1 = R \div 120 \quad (5)$$

where  $r_1$  = revolutions of spindle to feed stock and revolve turret,

$R$  = speed of spindle in revolutions per minute.

Now, to convert the revolutions required to feed stock into hundredths of the cam surface, it is necessary to know the time in seconds required to make one piece and the speed of the spindle. For example, let it be required to construct a table for laying out cams

# SCREW MACHINE CAMS

**TABLE I. CHANGE GEARS AND DATA FOR LAYING OUT CAMS.**  
**No. 00 BROWN & SHARPE AUTOMATIC SCREW MACHINE**

TIME IN SECONDS TO MAKE ONE PIECE.	GROSS PRODUCT IN TEN HOURS.	NET PRODUCT IN TEN HOURS GROSS MINUS 10% ON DRIVING SHAFT.	GEARS ON DRIVING SHAFT.	1ST GEAR ON STUD.	2ND GEAR ON STUD.	GEAR ON WORM SHAFT.	HUNDRETHS OF CAM SURFACE TO FEED STOCK.	SPINDLE SPEEDS	MIN. SEC. / REC.		BELT ON "A" "B" "C"
									MIN.	SEC.	
3	12000	10800	70				21	17	420	7	3-5
4	9000	8100	50				20	13	492	8.2	4-1
5	7200	6400	60				30	10	576	9.6	4-8
6	6000	5400	50				30	9	675	11.2	5-6
7	5142	4600	60				42	8	792	13.2	6-6
8	4500	4000	60				48	7	927	15.4	7-7
9	4000	3600	60				54	6	1087	18.1	9-1
10	3600	3200	40				40	5	1273	21.2	10-6
11	3272	2900	40				44	5	1492	24.8	12-4
12	3000	2700	40				45	5	1748	29.1	14-6
13	2769	2400	40				45	4	2048	34.1	17-1
14	2571	2300	30				42	4	2400	40.	20.
15	2400	2100	40				60	4			
16	2250	2000	30				48	4			
17	2117	1900	20				34	3			
18	2000	1800	30				54	3			
19	1894	1700	20				38	3			
20	1800	1600	20				40	3			
21	1714	1500	20				42	3			
22	1636	1450	20				44	3			
23	1565	1400	20				46	3			
24	1500	1350	20				48	3			
25	1440	1300	20				50	3			
26	1384	1250	20				52	3			
27	1333	1200	20				54	3			
28	1285	1150	20				56	3			
29	1241	1100	20				58	3			
30	1200	1050	20				60	3			
32	1125	1000	30	30	48	60	3				
34	1050	950	20	44	50	60	3				
36	1000	900	30	30	54	60	3				
38	947	850	20	30	58	60	3				
40	900	800	20	30	62	60	3				
42	857	775	20	30	66	60	3				
44	818	745	20	30	70	60	3				
46	782	700	20	30	74	60	3				
48	750	675	20	30	78	60	3				
50	720	650	20	30	82	60	3				
52	692	620	20	30	86	60	3				
54	666	600	20	30	90	60	3				
56	642	575	20	30	94	60	3				
58	620	550	20	30	98	60	3				
60	600	525	20	30	102	60	3				
62	571	500	20	30	106	60	3				
70	514	450	20	20	40	70	3				
77	457	420	20	20	44	70	3				
84	428	385	20	20	48	70	3				
91	395	355	20	20	52	70	3				

NUMBER OF REVOLUTIONS TO MAKE ONE PIECE.											
21	25	29	34	40	46	54	64	75	87	102	120
28	33	38	45	53	62	72	85	99	117	137	160
35	41	48	56	66	77	91	106	124	146	171	200
42	49	58	67	79	93	109	127	149	175	205	240
49	57	67	79	92	108	127	149	174	204	239	280
56	66	77	90	106	124	145	170	199	233	273	320
63	74	86	101	119	139	163	191	224	262	307	360
70	82	96	112	132	154	181	212	249	291	341	400
77	90	106	124	145	170	199	233	274	320	375	440
84	98	115	135	158	185	217	255	298	350	410	480
91	107	125	146	172	201	236	276	323	379	444	520
98	115	134	157	185	216	254	297	348	408	478	560
105	123	144	169	198	232	272	318	373	437	512	600
112	131	154	180	211	247	290	339	398	466	546	640
119	139	163	191	224	263	308	361	423	495	580	680
126	148	173	202	238	278	326	382	448	524	614	720
133	156	182	214	251	294	344	403	472	554	649	760
140	164	192	225	264	309	362	424	497	583	683	800
147	172	202	236	277	324	380	446	522	612	717	840
154	180	211	247	290	340	399	467	547	641	751	880
161	189	221	259	304	355	417	488	572	670	785	920
168	197	230	270	317	371	435	509	597	699	819	960
175	205	240	281	330	386	453	530	622	728	853	1000
182	213	250	292	343	402	471	552	647	757	887	1040
189	221	259	304	356	417	489	573	671	787	922	1080
196	230	269	315	370	433	507	594	696	816	956	1120
203	238	278	326	383	448	525	615	721	845	990	1160
210	246	288	337	396	463	543	636	746	874	1024	1200
217	254	297	348	407	478	559	654	768	899	1052	1240
224	262	307	359	422	494	580	679	796	932	1092	1280
232	270	316	371	449	525	616	721	846	990	1161	1360
239	279	326	381	449	525	616	721	846	990	1161	1360
248	285	336	395	475	556	652	764	895	1049	1229	1440
256	292	346	405	475	556	652	764	895	1049	1229	1440
264	300	356	415	475	556	652	764	895	1049	1229	1440
272	308	366	425	475	556	652	764	895	1049	1229	1440
280	316	376	435	475	556	652	764	895	1049	1229	1440
288	324	384	445	475	556	652	764	895	1049	1229	1440
294	334	403	473	554	649	761	891	1045	1224	1434	1680
302	342	412	495	581	680	797	934	1094	1282	1502	1760
310	350	420	517	607	711	833	976	1144	1340	1570	1840
318	358	428	539	629	733	865	1015	1188	1393	1631	1911
322	367	442	561	651	753	887	1037	1211	1412	1650	1929
327	374	450	583	673	775	909	1067	1231	1432	1670	1948
333	381	458	605	695	797	931	1089	1251	1452	1690	1968
339	389	466	627	717	819	953	1109	1271	1472	1710	1988
345	396	474	649	739	841	975	1129	1291	1492	1730	2008
351	404	482	671	761	863	997	1149	1311	1512	1750	2028
357	411	490	693	783	885	1019	1169	1331	1532	1770	2048
363	419	498	715	805	907	1039	1189	1351	1552	1790	2068
369	426	506	737	827	929	1059	1209	1371	1572	1810	2088
375	434	514	759	849	951	1079	1229	1391	1592	1830	2108
381	441	522	781	871	973	1099	1249	1411	1612	1850	2128
387	449	530	803	893	995	1119	1269	1431	1632	1870	2148
393	456	538	825	915	1017	1139	1289	1451	1652	1890	2168
400	464	546	847	937	1039	1159	1309	1471	1672	1910	2188
406	472	554	869	959	1061	1179	1329	1491	1692	1930	2208
412	480	562	891	981	1083	1199	1349	1511	1712	1950	2228
418	488	570	913	1003	1105	1219	1369	1531	1732	1970	2248
424	496	578	935	1025	1127	1239	1389	1551	1752	1990	2268
430	504	586	957	1047	1149	1259	1409	1571	1772	2010	2288
436	512	594	979	1069	1171	1279	1429	1591	1792	2030	2308
442	520	602	1001	1091	1193	1299	1449	1611	1812	2050	2328
448	528	610	1023	1113	1215	1319	1469	1631	1832	2070	2348
454	536	618	1045	1135	1237	1339	1489	1651	1852	2090	2368
460	544	626	1067	1157	1259	1359	1509	1671	1872	2110	2388
466	552	634	1089	1179	1281	1379	1529	1691	1892	2130	2408
472	560	642	1111	1201	1303	1399	1549	1711	1912	2150	2428
478	568	650	1133	1223	1325	1419	1569	1731	1932	2170	2448
484	576	658	1155	1245	1347	1439	1589	1751	1952	2190	2468
490	584	666	1177	1267	1369	1459	1609	1771	1972	2210	2488
496	592	674	1199	1289	1391	1479	1629	1791	1992	2230	2508
502	600	682	1221	1311	1413	1499	1649	1811	2012	2250	2528
508	608	690	1243	1333	1435	1519	1669	1831	2032	2270	2548
514	616	698	1265	1355	1457	1539	1689	1851	2052	2290	2568
5											

TABLE II. CHANGE GEARS AND DATA FOR LAYING OUT CAMS.  
No. O BROWN & SHARPE AUTOMATIC SCREW MACHINE

TIME IN SECONDS TO MAKE ONE PIECE	GROSS PRODUCT IN TEN HOURS	NET PRODUCT IN TEN HOURS GROSS MINUS 10%	FEED GEARS			HUNDRETHS OF CAM SURFACE TO FEED STOCK	SPINDLE SPEEDS	SPINDLE SPEEDS ON BELT TO MACH. ON PULLEY		
			GEAR ON A	1ST GEAR ON B	2ND GEAR ON B			GEAR ON C	FAST	B
									A	B
5	7200	6400	58	86	120	20	14	810	135	9.
6	6000	5400	58	86	120	24	12	988	16.4	10.9
7	5142	4600	58	86	120	28	10	1207	20.1	13.4
8	4500	4000	58	86	120	32	9	1474	24.5	16.3
9	4000	3600	58	86	120	36	8	1800	30	20.
10	3600	3200	58	86	120	40	7			
11	3272	2900	58	86	120	44	7			
12	3000	2700	58	86	120	48	6			
13	2760	2400	58	86	120	52	6			
14	2571	2300	58	86	120	56	5			
15	2400	2100	58	86	120	60	5			
16	2230	2000	58	86	120	64	5			
17	2117	1900	58	86	120	68	4			
18	2000	1800	58	86	120	72	4			
19	1894	1700	58	86	120	76	4			
20	1800	1600	58	86	120	80	4			
22	1616	1450	58	86	120	84	3			
24	1500	1350	58	86	120	88	3			
26	1384	1250	58	86	120	92	3			
28	1285	1150	58	86	120	96	3			
30	1200	1050	58	86	120	100	3			
32	1123	1000	58	86	120	104	3			
34	1059	950	58	86	120	108	3			
36	1000	900	58	86	120	112	3			
38	947	850	58	86	120	116	3			
40	900	800	58	86	120	120	3			
44	818	725	58	86	120	124	3			
48	759	675	58	86	120	128	3			
52	692	626	58	86	120	132	3			
56	642	575	58	86	120	136	3			
60	600	525	58	86	120	140	3			
65	553	490	58	86	120	144	3			
70	514	450	58	86	120	148	3			
75	480	430	58	86	120	152	3			
80	450	400	58	86	120	156	3			
90	400	360	58	86	120	160	3			
100	360	320	58	86	120	164	3			
110	327	290	58	86	120	168	3			
120	300	270	58	86	120	172	3			
135	266	235	58	86	120	176	3			
150	240	215	58	86	120	180	3			
165	218	195	58	86	120	184	3			
180	200	180	58	86	120	188	3			
195	184	165	58	86	120	192	3			
210	171	150	58	86	120	196	3			
225	160	140	58	86	120	200	3			
240	150	135	58	86	120	204	3			
270	133	120	58	86	120	208	3			
300	120	105	58	86	120	212	3			
330	109	100	58	86	120	216	3			
360	100	90	58	86	120	220	3			
390	92	80	58	86	120	224	3			

column under 182 as shown, and proceed to find the revolutions to feed stock, which according to Formula (3) equals:

$$R \div 60 = 182 \div 60 = 3.03 \text{ revolutions.}$$

Now, to find the hundredths of the cam surface to feed stock, divide the revolutions to feed stock by the total revolutions of the spindle required to make one piece. In this case we find that it requires 3.03

$$\frac{3.03}{30.3} = 0.099 \text{ or approximately 10 hundredths. It is always advisable 30.3}$$



TABLE III. CHANGE GEARS AND DATA FOR LAYING OUT CAMS.  
No. 2 BROWN & SHARPE AUTOMATIC SCREW MACHINE

TIME IN SECONDS TO MAKE ONE PIECE	GROSS PRODUCT IN 10 HOURS	NET PRODUCT IN 10 HOURS GROSS MINUS 10%	GEAR ON DRIVING SHAFT	1ST GEAR ON STUD	2ND GEAR ON STUD	GEAR ON WORM SHAFT	HUNDRETHS OF CAM SURFACE TO FEED STOCK	SPINDLE SPEEDS	PULLEY		SPINDLE SPEEDS											
									MIN.	SEC.	BELT TO MACH. ON PULLEY											
											FAST	A	C									
									2		120	277	519									
									2.467		148	342	789									
									3.033		182	421	1067									
									3.75		225	519	1315									
									4.617		277	640	16217									
									5.7		342	789	20									
									7.017		421	1067										
									8.65		519	1315										
									10.667		640	16217										
									13.15		789	20										
									16.217		973	1200										
									20		1200											
6	6000	5400	80	32	80	40	17				12	15	18	22	28	34	42	52	64	79	97	120
7	5142	4600	80	32	72	42	15				14	17	21	26	32	40	49	61	75	92	114	140
8	4560	4000	80	32	72	48	13				16	20	24	30	37	46	56	69	85	105	130	160
9	4000	3600	80	32	72	54	12				18	22	27	34	42	51	63	78	96	118	146	180
10	3600	3200	80	32	72	60	10				20	25	30	37	46	57	70	86	107	131	162	200
11	3272	2900	80	32	84	77	10				22	27	33	41	51	63	77	95	117	145	178	220
12	3000	2700	80	32	60	60	9				24	30	36	45	55	68	84	104	128	158	195	240
13	2764	2400	80	32	72	78	9				26	32	39	49	60	74	91	112	139	171	211	260
14	2571	2300	80	32	60	70	8				28	35	42	52	65	80	98	121	149	184	227	280
16	2250	2000	80	32	60	80	7				32	39	49	60	74	91	112	138	171	210	259	320
18	2000	1800	80	32	48	72	6				36	44	55	67	84	103	126	156	192	237	292	360
20	1800	1600	80	32	48	80	5				40	49	61	75	92	114	140	173	213	263	324	400
22	1636	1450	80	32	42	77	5				44	54	67	82	102	125	154	190	235	289	357	440
24	1500	1350	80	32	40	80	5				48	59	73	90	111	137	168	208	256	316	389	480
26	1384	1250	80	32	36	78	4				52	64	79	97	120	148	182	225	277	342	422	520
28	1285	1150	80	32	36	84	4				56	69	85	105	129	160	196	242	299	368	454	560
30	1200	1050	60	60	80	80	4				60	74	91	112	138	171	210	259	320	394	486	600
35	1028	925	60	60	72	84	3				70	87	106	131	162	199	246	303	373	460	568	700
40	900	800	60	60	51	72	3				80	99	121	150	185	228	281	346	427	526	649	800
45	800	700	60	60	48	72	3				90	111	136	169	208	256	316	389	480	592	730	900
50	720	625	60	60	48	80	3				100	124	152	187	231	285	351	432	533	657	811	1000
55	654	575	60	60	42	77	3				110	136	167	206	254	313	386	476	587	729	892	1100
60	600	525	60	60	60	60	3				120	148	182	225	277	342	421	519	640	789	973	1200
70	514	450	40	80	60	70	3				140	173	212	262	323	399	491	605	747	920	1135	1400
80	450	400	40	80	54	72	3				160	198	243	300	369	456	561	692	853	1052	1297	1600
90	400	350	40	80	48	72	3				180	222	273	337	415	513	631	778	960	1183	1459	1800
100	360	300	40	80	48	80	3				200	247	303	375	462	570	702	865	1067	1315	1622	2000
110	327	290	40	80	42	77	3				220	272	334	412	508	627	772	951	1173	1446	1784	2200
120	300	270	40	80	40	80	3				240	296	364	450	554	684	842	1038	1280	1578	1940	2400
135	266	240	36	72	40	90	3				270	333	409	506	623	769	947	1163	1440	1775	2180	2700
150	240	210	36	80	40	90	3				300	370	455	562	692	855	1052	1297	1600	1972	2432	3000
165	218	190	36	77	35	90	3				330	407	500	619	752	940	1158	1427	1760	2170	2675	3300
180	200	180	36	84	35	90	3				360	444	546	675	831	1026	1263	1557	1920	2367	2919	3600
195	184	160	32	78	36	96	3				390	481	591	731	900	1112	1368	1687	2080	2564	3162	3900
210	171	150	24	80	40	84	3				420	518	637	788	970	1197	1474	1817	2240	2762	3406	4200
225	160	140	32	90	36	96	3				450	555	682	844	1039	1283	1579	1946	2400	2959	3649	4500
240	150	135	24	80	40	96	3				480	592	728	900	1108	1368	1684	2076	2560	3156	3892	4800
270	133	120	32	72	24	96	3				540	666	819	1013	1247	1539	1895	2336	2880	3551	4379	5400
300	120	105	24	80	32	96	3				600	740	910	1125	1395	1710	2105	2595	3200	3945	4865	6000
330	109	95	24	89	32	96	3				660	814	1001	1238	1524	1881	2316	2855	3520	4340	5352	6600
360	100	90	22	88	32	96	3				720	888	1092	1350	1662	2052	2526	3144	3840	4734	5838	7200
390	92	80	24	78	24	96	3				780	962	1183	1463	1801	2223	2737	3374	4160	5129	6325	7800
420	85	75	24	84	24	96	3				840	1036	1274	1575	1939	2394	2947	3633	4480	5523	6811	8400
450	80	70	24	90	24	96	3				900	1110	1365	1688	2078	2565	3158	3893	4800	5918	7298	9000
480	75	65	24	85	22	96	3				960	1184	1455	1800	2216	2730	3358	4152	5120	6312	7784	9600

to add one hundredth for revolving the turret so that it will be securely locked in position before the tools advance on the work; then in this case it will require 11 hundredths to revolve the turret. Owing to the diameter of the cam roll there should never be less than three hundredths allowed for revolving the turret, irrespective of the speed at which the cam shaft is running.

Tables I to III give the change gears and data for laying out cams for the Nos. 00, 0 and 2 automatic screw machines. When the speed at

TABLE IV. CHANGE GEARS AND DATA FOR LAYING OUT CAMS.  
No. 00 TURRET FORMING AND CUTTING-OFF MACHINE

TIME IN SECONDS TO MAKE ONE PIECE.	GROSS PRODUCT IN TEN HOURS.	NET PRODUCT IN TEN HOURS. GROSS MINUS 10%.	GEAR ON DRIVING SHAFT.	1st GEAR ON STUD.	2nd GEAR ON STUD.	GEAR ON WORM SHAFT.	HUNDRETHS OF CAMS PER FEED STOCK.	SPINDLE SPEEDS. MIN. SEC. X SEC.	NUMBER OF REVOLUTIONS TO MAKE ONE PIECE											
									4 1/2	5	6	7 1/2	8 1/2	10	12	15	18	20	24	30
									420	540	690	890	1140	1460	1870	2400	3060	3825	4710	5715
3	12000	10800	70			21	17	21	27	34	44	57	73	93	120	160				
4	9000	8100	50			20	13	28	36	46	59	76	97	125	166	200				
5	7200	6400	50			30	10	35	45	58	74	95	122	156	200	240				
6	6000	5400	50			30	9	42	54	69	89	114	146	187	240	300				
7	5142	4600	66			42	8	49	63	81	104	133	170	218	280	360				
8	4500	4000	66			48	7	56	72	92	119	152	195	249	320	400				
9	4000	3600	66			54	6	63	81	104	134	171	219	280	360	450				
10	3600	3200	40			40	5	70	90	115	148	190	243	312	400	500				
11	3272	2900	40			44	5	77	99	127	163	209	268	343	440	550				
12	3000	2700	40			48	5	84	108	138	178	228	292	374	480	600				
13	2769	2400	40			52	4	91	117	150	193	247	316	405	520	650				
14	2571	2300	30			42	4	98	126	161	208	266	341	436	560	700				
15	2400	2100	40			60	4	105	135	173	222	285	365	467	600	750				
16	2250	2000	30			48	4	112	144	184	237	304	389	499	640	800				
17	2117	1900	20			34	3	119	153	196	252	323	414	530	680	850				
18	2000	1800	30			54	3	126	162	207	267	342	438	561	720	900				
19	1894	1700	20			38	3	133	171	219	282	361	462	592	760	950				
20	1800	1600	20			40	3	140	180	230	297	380	487	623	800	1000				
21	1714	1500	20			42	3	147	189	242	311	399	511	654	840	1050				
22	1636	1450	20			44	3	154	198	253	326	418	535	686	880	1100				
23	1565	1400	20			46	3	161	207	265	341	437	560	717	920	1150				
24	1500	1350	20			48	3	168	216	276	356	456	584	748	960	1200				
25	1440	1300	20			50	3	175	225	288	371	475	608	779	1000	1250				
26	1384	1250	20			52	3	182	234	299	386	494	633	810	1040	1300				
27	1333	1200	20			54	3	189	243	311	400	513	657	841	1080	1350				
28	1285	1150	20			56	3	196	252	322	415	532	681	872	1120	1400				
29	1241	1100	20			58	3	203	261	334	430	551	706	904	1160	1450				
30	1200	1050	20			60	3	210	270	345	445	570	730	935	1200	1500				
32	1125	1000	30	30	48	60	3	224	288	368	475	608	779	997	1280	1600				
34	1050	950	20	44	50	60	3	238	306	391	504	646	827	1060	1360	1700				
36	1000	900	30	30	54	60	3	252	324	414	534	684	876	1122	1440	1800				
38	947	850	20	30	58	60	3	266	342	437	564	722	925	1184	1520	1900				
40	900	800	20	30	60	60	3	280	360	460	593	760	973	1247	1600	2000				
42	857	775	20	30	62	60	3	294	378	483	623	798	1022	1309	1680	2100				
44	818	745	20	30	64	60	3	308	396	506	653	836	1071	1371	1760	2200				
46	782	700	20	30	66	60	3	322	414	529	682	874	1119	1434	1840	2300				
48	750	675	20	30	68	60	3	336	432	552	712	912	1168	1496	1920	2400				
50	720	650	20	30	70	60	3	350	450	575	742	950	1217	1558	2000	2500				
52	692	620	20	30	72	60	3	364	468	598	771	998	1265	1621	2080	2600				
54	656	600	20	30	74	60	3	378	486	621	801	1026	1314	1683	2160	2700				
56	642	575	20	30	76	60	3	392	504	644	831	1064	1363	1745	2240	2800				
58	620	550	20	30	78	60	3	406	522	667	860	1102	1411	1808	2320	2900				
60	600	525	30	21	84	70	3	420	540	690	890	1140	1460	1870	2400	3000				
63	571	500	30	20	84	70	3	441	567	725	935	1197	1533	1963	2520	3100				
70	514	450	20	20	90	70	3	490	630	805	1038	1330	1703	2182	2800	3500				
77	467	420	20	20	96	70	3	539	693	886	1142	1463	1874	2400	3080	3800				
84	428	385	20	20	102	70	3	588	756	966	1246	1596	2044	2618	3360	4100				
91	395	355	20	20	108	70	3	637	819	1047	1350	1729	2214	2836	3640	4500				

which the spindle is to be run for any certain job, and the number of revolutions required to complete one piece, are known, the gears, product in ten hours and the time in seconds to make one piece as well as the number of hundredths of the cam surface required to feed the stock and revolve the turret, are found in the left-hand columns of the table, the total revolutions required to make one piece being given in the




TABLE VI. CHANGE GEARS AND DATA FOR LAYING OUT CAMS.  
No. 2 TURRET FORMING AND CUTTING-OFF MACHINE

	TIME IN SECONDS TO MAKE ONE PIECE.	GROSS PRODUCT IN 10 HOURS.	NET PRODUCT IN 10 HOURS—GROSS MINUS 10% GEAR ON DRIVING SHAFT.	1st GEAR ON STUD.	2nd GEAR ON STUD.	GEAR ON WORM SHAFT	HUNDRETHS OF CAM SURFACE TO FEED STOCK.	SPINDLE SPEEDS.							
								MIN.	SEC.						
								180	263						
6	6000	5400	80	32	80	40	17			18	26	39	56	82	120
7	5142	4600	80	32	72	42	15			21	31	45	66	96	140
8	4500	4000	80	32	72	48	13			24	35	51	75	109	160
9	4000	3600	80	32	72	54	12			27	39	58	84	123	180
10	3600	3200	80	32	72	60	10			30	44	64	94	137	200
11	3272	2900	80	32	84	77	10			33	48	71	103	151	220
12	3000	2700	80	32	60	60	9			36	53	77	112	164	240
13	2769	2400	80	32	72	78	9			39	57	83	122	178	260
14	2571	2300	80	32	60	70	8			42	61	90	131	192	280
16	2250	2000	80	32	60	80	7			48	70	103	150	219	320
18	2000	1800	80	32	48	72	6			54	79	116	169	246	360
20	1800	1600	80	32	48	80	5			60	88	128	187	274	400
22	1636	1450	80	32	42	77	5			66	96	141	206	301	440
24	1500	1350	80	32	40	80	5			72	105	154	225	328	480
26	1384	1250	80	32	36	78	4			78	114	167	244	356	520
28	1285	1150	80	32	36	84	4			84	123	180	262	383	560
30	1200	1050	60	60	80	80	4			90	131	193	281	410	600
35	1028	925	60	60	72	84	3			105	153	225	328	479	700
40	900	800	60	60	54	72	3			120	175	257	375	547	800
45	800	700	60	60	48	72	3			135	197	289	422	616	900
50	720	625	60	60	48	80	3			150	219	321	468	684	1000
55	654	575	60	60	42	77	3			165	241	353	515	753	1100
60	600	525	40	80	60	60	3			180	263	385	562	821	1200
70	514	450	40	80	60	70	3			210	307	449	656	958	1400
80	450	400	40	80	54	72	3			240	351	513	749	1095	1600
90	400	350	40	80	48	72	3			270	394	577	843	1231	1800
100	360	300	40	80	48	80	3			300	438	642	937	1368	2000
110	327	290	40	80	42	77	3			330	482	706	1030	1505	2200
120	300	270	40	80	40	80	3			360	526	770	1124	1642	2400
135	266	240	36	72	40	90	3			405	592	866	1265	1847	2700
150	240	210	36	80	40	90	3			450	657	963	1405	2052	3000
165	218	190	36	77	35	90	3			495	723	1059	1546	2258	3300
180	200	180	36	84	35	90	3			540	789	1155	1686	2463	3600
195	184	160	32	78	36	96	3			585	855	1251	1827	2668	3900
210	171	150	24	80	40	84	3			630	920	1348	1967	2873	4200
225	160	140	32	90	36	96	3			675	986	1444	2108	3079	4500
240	150	135	24	80	40	96	3			720	1052	1540	2248	3284	4800
270	133	120	32	72	24	96	3			810	1183	1733	2529	3694	5400
300	120	105	24	80	32	96	3			900	1315	1925	2810	4105	6000
330	109	95	24	88	32	96	3			990	1446	2118	3091	4515	6600
360	100	90	22	88	32	96	3			1080	1578	2310	3372	4926	7200
390	92	80	24	78	24	96	3			1170	1709	2503	3653	5336	7800
420	85	75	24	84	24	96	3			1260	1841	2695	3934	5747	8400
450	80	70	24	90	24	96	3			1350	1972	2888	4215	6157	9000
480	75	65	24	88	22	96	3			1440	2104	3080	4496	6568	9600

Constructing the Rise on Cams

The rise on the cam should be such that the tools will gradually slow up as they approach the work. It is not necessary to lay out a uniform curve for the rise, as in most cases the cam rotates slowly, but when the cam is required to make one revolution in less than 5 seconds on the No. 0 or No. 2 screw machine, a curve for a more uniform speed should be constructed.

TABLE VII. DIMENSIONS OF CAMS AND CAM LEVERS



No. of Machine	00		0		2	
	Lead	Cross-slide	Lead	Cross-slide	Lead	Cross-slide
Principal Dimensions						
Dimensions in Inches						
A	2 1/2	2 1/4	3 1/4	3	4	3 1/2
B	1 3/8	1	2	1 1/4	2 3/4	1 3/4
C	1	1	1 1/8	1 1/8	1 1/4	1 1/4
D	1/4	1/4	5/16	5/16	5/16	5/16
E	15/16	15/16	1	1	1 1/8	1 1/8
F	1/2	1/2	9/16	9/16	5/8	5/8
G	1/4	1/4	5/16	5/16	3/8	3/8
H	3 5/16	2 3/8	3 3/4	2 3/4	4.5	3.083
I	3 11/16	3 1/8	4 1/4	3 11/16	4.208	4 1/4
J	1 1/4	7/8	1	1 1/4	3 1/2	1 3/8

Generally the rise can be abrupt for about three-quarters of the way, and then gradually slow down as the tool approaches the work. A good method of laying out a curve of this form is shown in Fig. 4. The reason for making a curve of this form is that less time is necessary for one tool to clear another, which sometimes makes quite a considerable difference in the time required to produce one piece

To construct the rise, proceed as follows: Lay off on line *H* a distance *D* from the point *a*. Distance *D* varies with the clearance necessary between the turret and cross-slide tools. Then draw line *BC* at right angles to *H*. With *a* as a center, and a radius *R* describe an arc intersecting line *BC* at point *b*; again with *R* as a radius, and a center at *b*, describe the rise. Join the rise and the small diameter dwell of

TABLE VIII. DIMENSIONS FOR LAYING OUT CAM RISE FOR No. 00 BROWN & SHARPE AUTOMATIC SCREW MACHINE

Number of Seconds to make one Piece	Lead	Front and Back Cams
	D	R
From 3 to 5 seconds.....	$\frac{29}{32}$	$1\frac{1}{8}$
From 6 to 12 seconds.....	$\frac{3}{4}$	$1\frac{1}{4}$
From 13 to 30 seconds.....	$\frac{5}{8}$	$1\frac{1}{4}$

the cam with a circle having a diameter equal to the diameter of the roll. The distance *r* should then be measured off and recorded on the drawing to be used by the toolmaker when laying out the cams. The various values for the dimensions given in Fig. 4 for the rise, that have been found suitable, are specified in Tables VIII, IX and X.

#### Constructing Drop on Cams

The drop on the cams should be such that the cross-slides will drop back without shock. The turret slide drops back on a cushion spring,

TABLE IX. DIMENSIONS FOR LAYING OUT CAM RISE FOR No. 0 BROWN & SHARPE AUTOMATIC SCREW MACHINE

Number of Seconds to make one Piece	Lead		Front and Back Cams	
	D	R	D	R
From 5 to 12 seconds....	$1\frac{1}{8}$	$1\frac{15}{16}$	$1\frac{1}{8}$	$1\frac{1}{2}$
From 13 to 30 seconds....	$1\frac{1}{8}$	$2\frac{3}{8}$	$1\frac{1}{8}$	2
From 32 to 60 seconds....	1	$3\frac{1}{4}$	$1\frac{1}{8}$	3

thus allowing the drop on the lead cam to be more abrupt, on the No. 0 and No. 2 screw machines, than it is on the front and rear cams. This is also true of the No. 00 machine, but as the drop is not great, very little time would be saved by using a smaller angle of drop for the lead than for the cross-slide cams. Referring to Fig. 4, it can be seen that the lever arm swings about a pivot, so that, to have a uniform drop, a special curve should be constructed. But, as this drop would be more difficult to make than a straight drop, a straight or angular drop is adopted. This gives the drop of the arm a variable motion, as can be seen by referring to Fig. 4; the roll will drop quickly

to about the point *e*, then slow up and then increase in speed as it approaches the bottom. The cross-slides are forced back by a spring which serves to keep the roll in contact with the cam. The drop on

TABLE X. DIMENSIONS FOR LAYING OUT CAM RISE FOR No. 2 BROWN & SHARPE AUTOMATIC SCREW MACHINE

Number of Seconds to make one Piece	Lead		Front and Back Cams	
	D	R	D	R
From 6 to 14 seconds..	$1\frac{7}{8}$	$2\frac{7}{16}$	$1\frac{1}{2}$	$1\frac{1}{2}$
From 15 to 40 seconds..	$1\frac{1}{2}$	$2\frac{3}{8}$	$1\frac{1}{2}$	$1\frac{1}{8}$
From 45 to 90 seconds..	$1\frac{1}{2}$	$2\frac{1}{2}$	$1\frac{1}{8}$	$1\frac{1}{8}$
From 100 to 180 seconds.	$1\frac{3}{8}$	$3\frac{1}{2}$	$1\frac{1}{8}$	$2\frac{1}{16}$

the cam should not be laid off from a circle as shown by the dotted lines at *c*. This would mean that the roll would drop slower when dropping a short distance than when dropping a greater distance. The drop should be laid off from the hundredth line where the operation




Fig. 4. Method of Laying out Rise and Fall on Cams

finishes as shown by the angle *A*. This assures the drop always being of the same speed, irrespective of the distance through which it has to drop. The following angles of drop have been found suitable for the given number of seconds required to make one piece.

DROP ON CAMS FOR No. 00 BROWN & SHARPE AUTOMATIC  
SCREW MACHINE

Number of Seconds to make One Piece	Lead, Front and Back
From 3 to 5 seconds	$A = 20$ degrees
From 6 to 12 seconds	$A = 15$ degrees
From 13 to 30 seconds	$A = 10$ degrees

DROP ON CAMS FOR No. 0 BROWN & SHARPE AUTOMATIC  
SCREW MACHINE

Number of Seconds to make One Piece	Lead	Front and Back
From 5 to 12 seconds	$A = 17$ degrees	16 degrees
From 13 to 30 seconds	$A = 14$ degrees	13 degrees
From 32 to 60 seconds	$A = 10$ degrees	9 degrees

DROP ON CAMS FOR No. 2 BROWN & SHARPE AUTOMATIC  
SCREW MACHINE

Number of Seconds to make One Piece	Lead	Front and Back
From 6 to 14 seconds	$A = 16$ degrees	22 degrees
From 15 to 40 seconds	$A = 14$ degrees	19 degrees
From 45 to 90 seconds	$A = 12$ degrees	16 degrees
From 90 to 180 seconds	$A = 10$ degrees	13 degrees

Clearance for Tools

In laying out a set of cams it is sometimes found necessary to make allowance for one tool to clear another, the amount of clearance necessary being determined by the diameter or width of tool used in the turret and the position of the cross-slide tools relative to the work. When determining the amount of clearance necessary, the rise and drop on the lead cam is disregarded and the rises and drops on the front and rear cams are taken into consideration. To determine the rise and drop to use, make a rough lay-out of the various operations to be performed and also settle upon the approximate number of revolutions to complete one piece. The revolutions are then converted into seconds as was previously explained. To explain clearly the method used, we will take a practical example. Assume that it is required to make a brass screw as shown in Fig. 5. This screw is made from  $\frac{1}{4}$ -inch round brass rod, and can be made to advantage on the No. 00 Brown & Sharpe automatic screw machine, using a spindle speed of 2400 R. P. M. backward and forward. Assume that it is required to find the amount of clearance necessary for the die holder to pass the circular form and cut-off tools. Draw in the form tool in position on the screw as shown to the left in Fig. 5, and also an outline of the toolpost. Then lay out the die holder in position to start on the screw, as shown by the dotted lines. If a releasing die holder is used, take the diameter over the heads of the screws in the holder, but if a "draw-out" type is used, the diameter of the cap is taken. In this case, as the screw is threaded up to the shoulder, a releasing die holder will be used. In Fig. 5 it can be seen that the die holder cannot advance on the screw until the form tool drops back a distance  $B$ , but as  $B$  is the actual distance,



it will be necessary to add an extra amount to insure that the die holder can advance without coming in contact with the circular form tool. The extra amount of clearance necessary varies with the type of tool used. The following dimensions give the approximate amounts that should be added to the actual clearance for the type of tools specified:

Type of Tool	Extra Amount of Clearance
Drill holders .....	from 1/8 to 3/16 inch
Box-tools (with V-supports).....	from 1/8 to 1/4 inch
Box-tools (with supporting bushing).....	from 3/16 to 5/16 inch
Button die holders (draw-out type).....	from 3/16 to 5/16 inch
Button die holders (releasing type).....	from 1/4 to 1/2 inch

To find the amount necessary for clearance, make a diagram as shown in Fig. 6, laying out the drop on the front cam as shown. Then add, say,  $\frac{1}{4}$  inch, to dimension *B* and measure down from the point where the lobe finishes, scribing an arc of a circle through the point




Fig. 5. Diagram illustrating Method of Finding Clearance for Die Holder

thus located, as shown. Then with a radius equal to the radius of the cam roll, describe a circle touching the arc drawn and the drop on the cam. Join the center of the roll with the center of the cam circle by a straight line. The clearance is then measured off in hundredths as shown by dimension *H*. The starting point of the lobe on the lead cam for threading will be at the hundredth line *D* and the intervening space between the lines *D* and *E* will be the amount necessary for clearance.

When the cutting-off operation follows the threading operation it will also be necessary to allow for clearance. To find the amount of clearance necessary for the die holder to clear the circular cut-off tool, proceed as follows: Make a lay-out as shown to the right in Fig. 5 and measure off the distance *C*. Add  $\frac{1}{4}$  inch to this and lay off this dimension from the starting point *A* of the rear cam as shown in Fig. 6, drawing an arc of a circle as before. Then draw a circle the diameter of which is equal to the diameter of the roll, touching the arc drawn and the rise on the cam, and measure off the clearance *H* as was previously explained. The thread lobe would finish at the hundredth

line *F* and the cut-off tool start at the line *A*. Clearance should also be allowed between the dropping back of the cut-off tool and the feeding of the stock. To find the amount of clearance necessary add  $\frac{1}{8}$  inch to the largest radius of the stock used and proceed as previously explained.

To make this explanation more complete, the various steps followed when designing a set of cams will be given.

#### Designing and Laying out Cams

When designing a set of cams the speed of the spindle best suited for the size of stock and nature of material should first be decided upon.





Fig. 6. Method of Determining Clearance on Cross-slide Cams

The tables for surface speeds given in MACHINERY'S Reference Book No. 99, "Automatic Screw Machine Practice—Operation of the Brown & Sharpe Automatic Screw Machine," will be found convenient for this purpose. The quickest and best method of making the piece should next be considered, and a diagram made of the tools to be used in the turret as shown at *A*, Fig. 7, leaving from  $\frac{1}{8}$  to  $\frac{3}{16}$  inch clearance between the rear face of the tool-holder and the face of the turret. This amount, of course, varies to a considerable extent, depending on the length of the shank and body of the tool, and also on the distance that the work projects from the chuck. When the shank of the tool is short, care should be taken to see that the clamping devices in the turret have a good grip on the shank of the tool. The diagram

of the circular tools applied to the work should also be made as shown at *B*, Fig. 7. The feeds for the various operations are then decided upon and divided into the length of cut which will give the number of revolutions required for the various operations. The total number of revolutions to complete one piece is found by adding together the number of revolutions for each cut, for revolving the turret, feeding the stock and, in some cases, reversing the spindle; an approximate number of revolutions should also be added for clearance. When the approximate number of seconds to complete one piece has been obtained we make a diagram of the rise and drop on the cam as shown in Fig. 6. To ascertain the exact number of revolutions required for clearance, if the approximate number of revolutions as allowed for



$$1 \frac{9}{16} + \frac{7}{8} = 2 \frac{7}{16} \text{ inch.}$$

$$2 \frac{7}{16} \text{ inch} - 1 \frac{3}{4} \text{ inch} = \frac{11}{16} \text{ inch.}$$

In Fig. 8 is given a method of laying out the cams for the screw shown in Fig. 7. This method is commendable, as it can be seen whether the tools will clear one another better than if the cams were drawn separately instead of one on top of the other. If the foregoing suggestions are followed, very little trouble will be encountered in designing a set of cams. The example as given is for making screws, but the same method can be followed in making any other class of work. After the cams have been designed, a tracing should be made and kept




Fig. 8. Commendable Method of Laying out Cams

for reference. (See Fig. 40, Part I of this treatise, MACHINERY'S Reference Book No. 99.)

#### Practical Points in Designing Cams and Special Tools

1. Use the highest spindle speeds that the various tools will stand.
2. Use the arrangement of circular tools best suited for the class of work. (See Reference Book No. 101.)
3. Decide on the quickest and best method of arranging the operations before designing the cams.
4. Do not use turret tools for forming when the cross-slide tools can be used to better advantage.
5. Do not use a circular cut-off tool without top rake when cutting Norway iron, machine steel, etc.

6. Make the shoulder on the circular cut-off tool large enough so that the clamping screw will grip firmly.
7. When chips clinging to the work are objectionable, the circular form tool should be turned up-side-down and placed on the rear cross-slide.
8. Do not use too narrow a cut-off blade.
9. Allow 0.005 to 0.010 inch for the circular tools to approach the work and 0.003 to 0.005 inch for the cut-off tool to pass the center.
10. When cutting off work large in diameter, the feed on the cut-off tool should be increased until near the end of the cut where the piece breaks off. After it breaks off, the feed should again be increased until the tool has passed the center.
11. When a thread is cut up to a shoulder, the piece should be grooved or necked to make allowance for the lead on the die. This requires an extra projection on the form tool and also an extra amount of rise on the cam.
12. Use circular form and cut-off tools made from high-speed steel when cutting Norway iron, machine steel, etc.
13. Use a fine feed and high spindle speed for all cutting tools.
14. Allow sufficient clearance for tools to pass one another.
15. Always make a diagram of the cross-slide tools in position on the work when difficult operations are to be performed; it is also necessary to make a diagram of the tools held in the turret.
16. Do not drill a hole the depth of which is more than  $2\frac{1}{2}$  times the diameter of the drill, but use two or more drills as required. If there are not sufficient holes in the turret, drop the drill back clear of the hole, and advance it into the hole again.
17. Do not run a drill at a slow speed.
18. When the turret tools operate further in than the face of the chuck, see that they will clear the chute when revolving the turret.
19. See that the body of all turret tools will clear the side of the chute when revolving the turret.
20. Do not use a box-tool for a roughing cut. Use a hollow mill.
21. Do not use a box-tool with soft supports. Use solid supports only on cold-drawn or finished stock.
22. The rise on the thread lobe should be reduced so that the spindle will reverse when the die or tap holder is drawn out.
23. When threading Norway iron, machine steel, etc., if the spindle speed used for the other tools is too high for threading, use a special threading attachment. (See MACHINERY'S Reference Book No. 104.)
24. When bringing another tool into position after a threading operation, allow clearance before revolving the turret.
25. Make provision to revolve the turret rapidly, especially when pieces are being made in from three to five seconds and when only a few tools are used in the turret. It is sometimes convenient to use two sets of tools.
26. When using a belt-shifting attachment for threading, clearance should be allowed, as it requires extra time to shift the belt.

27. When laying out a set of cams for operating on a piece which requires to be slotted, cross-drilled or burred, allowance should be made on the lead cam so that the transferring arm can descend and ascend to and from the work without coming in contact with any of the turret tools.

28. Always allow a vacant hole in the turret when it is necessary to use the transferring arm.

29. Use standard tools whenever possible.

30. When designing special tools allow as much clearance as possible. Do not make them so that they will just clear, as errors sometimes turn up, causing trouble.

31. When designing special tools having intricate movements, avoid springs as much as possible, and use positive actions.

## CHAPTER II

### CAMS FOR SCREW-SLOTTING ATTACHMENTS

The Brown & Sharpe Mfg. Co., Providence, R. I., has designed a number of standard and special attachments for its automatic screw machines. These attachments are used for performing various second operations on a piece of work, such as slotting, milling, cross-drilling and burring, at the same time that another piece is being operated on by the cross-slide and turret tools. Thus extra operations are performed without taking additional time.

While the attachments—as such—are widely known, the methods of laying out the cams for operating them are no doubt unfamiliar to a large number of operators and mechanics in general, and, therefore, a description of the methods of laying out the cams for one of these attachments should be of general interest. The best known attachment designed by the Brown & Sharpe Mfg. Co. is its screw-slotting attachment, which is shown in Fig. 9.

#### Screw-slotting Attachment for the No. 00 Machine

The screw-slotting attachment is fastened to a boss, provided for this purpose on the machine, by two cap-screws. An apron, which is also an additional part, carries the arbor *C* to which the transferring arm *F* is attached. The transferring and advancing cam levers *D* and *E* are also fastened to bosses on this apron by cap-screws. These levers are operated by the advancing and transferring cams *J* and *K*. A block *H* is fastened to the arm *F*, and a slotting bushing or carrier for the screw is driven into it. This bushing grips the screw and holds it while the slotting saw, held on an arbor and driven by a pulley through bevel gears, mills the slot in the head.

The design and action of the device is, in detail, as follows: The transferring lever *D* is kept in contact with the cam by means of two




Fig. 9. Assembly Views of Screw-slottting Attachment for the No. 00 Brown & Sharpe Automatic Screw Machine

springs *L* and *M*. The advancing lever *E* is kept in contact with the advancing cam by the spring *N*, located on the transferring-arm rod *C*. This open-wound spring presses against the boss *O* on the attachment and the washer *P*, this latter being held up against a ball retainer *Q* which, in turn, is forced against a washer held to the arbor *C* by a cone-pointed screw. The lever *E* does not bear directly against the thrust-washer *R* to advance the arm, but holds a set-screw *S* which can be adjusted in and out and locked with a headless screw. This screw *S*, in conjunction with the screw *S*<sub>1</sub>, is used for varying the depth of the slot in the head of the screw.




Fig. 10. Turret and Cross-slide Cams for Making a Steel Screw

The transferring lever *D* is connected to a block *D*<sub>1</sub>, which is fastened to the rod *C* by a screw *C*<sub>1</sub>. This block connects arm *F* with lever *D*. The arms of lever *D* and the arm *F* are so proportioned that a small rise of about 1½ inch on the cam in this case is sufficient to carry the slotting bushing from the chuck up to the saw through the path indicated in the engraving. When arm *F* drops down into a position in front of the chuck, it is stopped at the desired point by a set-screw *E*<sub>1</sub>, which rests on a block *F*<sub>1</sub>, attached to the machine. When the arm moves up into a position in front of the saw, it is stopped by a set-screw *G*<sub>1</sub>, which bears against a block *H*<sub>1</sub>, fastened to the attachment. The set-screws *G*<sub>1</sub> and *E*<sub>1</sub> are used for setting the slotting bushing accu-



ately. The slotting bushing is shown at  $I_1$  in position in block  $H$ . The shank of this bushing is tapered one-half inch to the foot and is driven into the block. Block  $H$  is held to the arm by a cap-screw  $J_1$ . When the slot in the screw has been cut and arm  $F$  drops back, the screw is removed from the bushing, which has a slot cut in it, by the ejector  $K_1$ , which is simply a piece of sheet steel fastened to the attachment.

#### Laying out a Set of Cams for a Screw-slottting Operation

Undoubtedly the method of setting and operating this screw-slottting attachment can best be described by taking a practical example. Suppose it is necessary to make the shouldered steel screw shown at  $A$  in Fig. 10 on a No. 00 Brown & Sharpe automatic screw machine. To pro-




Fig. 11. Diagram used in determining the Rises on the Transferring and Advancing Cams

ceed: First design the cross-slide and turret cams, making allowance for one empty hole in the turret, thus enabling the transferring arm to drop down and pick up the screw while it is being cut off. It will not be necessary to describe the method of laying out the turret and cross-slide cams, as this has been described in the previous chapter, so we will confine our attention to the calculations necessary in laying out the transferring and advancing cams for removing and slotting the screw.

Before proceeding with the laying out of these cams, it is necessary to make a diagram such as is shown in Fig. 11. Here a diagrammatical view of the necessary movement of the transferring and advancing levers is shown. To the right of the illustration is a diagram of the movement of the transferring arm and lever. For the slotting attachment, the transferring arm does not have to dwell at any intermediate

point between the chuck and the slotting saw, so that no calculation is necessary to find the rise on the cam—the full rise or  $1\frac{1}{8}$  inch being sufficient to lift the slotting bushing from the chuck to the slotting saw. To the left of the illustration is a diagram in which is indicated the least and greatest possible distances between the face of the turret and the chuck, and also the position of the screw-slotting arbor relative to the chuck. Below this, the transferring arm is shown in position on the screw. Here it can be seen that the lobes for placing the bushing on the work and advancing it to the saw will be of the same height, as the distance  $\frac{3}{32}$  inch is considerably less than the adjustment provided for the screw-slotting attachment; this adjustment is equal to  $\frac{5}{16}$  inch on each side of the center line.

When the rises or the heights of the various lobes on the cams have been determined, the next problem is to determine their relative positions, or, in other words, the starting and finishing points of the lobes on the transferring and advancing cams, respectively.

#### Laying out the Transferring and Advancing Cams

The location hole *B* in the cam shown in Fig. 10 is not used in the transferring and advancing cams, so that these cams, when made, can be shifted around to the desired position. However, it is best to start from some predetermined point when laying out the cams. The least confusion will result if the point at which the piece breaks off is used for the point at which the bushing is located on the work. This point, of course, cannot be determined exactly, but it is easy to locate it approximately.

The method of determining this is as follows: Taking the screw shown at *A*, in Fig. 10, as an example, we will assume that it will break off when the teat is 0.010 inch in diameter. (This screw is made in 9 seconds and requires 360 revolutions of the work spindle, which in this case is rotated at 2400 R. P. M.) Then assuming that the length of the bevel on the cut-off tool, or distance *C*, Fig. 3, equals 0.010 inch, and that the amount to pass the center of the work equals 0.005 inch, we find that the distance the point of the cut-off tool will have to travel after the piece breaks off equals  $0.010 + 0.005 + 0.005 = 0.020$  inch. To find the hundredth line on the cam circle where the screw is supposed to break off, divide the travel (in inches) of the cut-off tool, still to be completed after the piece is cut-off, by the feed of the cut-off tool per revolution of the work. (See cut-off cam, Fig. 10.) Thus,

$$\frac{0.020}{0.00166} = 12.05 \text{ revolutions.}$$

In other words, it requires 12 revolutions of the spindle after the piece is cut off before the cut-off tool reaches the end of its travel. The hundredths of cam surface equivalent to 12 revolutions of the spindle

are  $\frac{12 \times 100}{360} = 3\frac{1}{2}$  hundredths, approximately. Therefore we assume

that the screw will break off when the center of the cross-slide roll is

at  $94\frac{1}{2}$  hundredths. As this is where the screw will break off, it is necessary to have the bushing on the work a moment previous to this. In this case we will allow  $\frac{1}{2}$  hundredth, but it is usually best to allow one hundredth of the cam surface to give the arm time to steady itself after forcing the bushing onto the work.

Having determined the point where the slotting bushing should be located on the work we can proceed to lay out the transferring and advancing cams. The method of laying out these cams is shown in Fig. 12. As previously determined, the advancing cam is not cut down below the outer circumference except for the rise for feeding the screw to the saw and dropping back, so a circle is drawn with a  $2\frac{1}{4}$ -inch radius as shown, which represents the largest diameter of the cams. A circle *A*, representing the path of the center of the transferring lever, is next drawn. Then a vertical line *B*, representing the path of the center of the advancing cam, is drawn. When this line and circle have been drawn, we have the relative positions of the transferring and advancing rolls. The transferring roll is  $\frac{1}{2}$  inch in diameter, while the advancing roll is  $\frac{3}{4}$  inch, on the No. 00 machine only.

To find the starting and finishing points on the cams, proceed as follows: Draw a circle *C* representing the advancing roll on the hundredth line marked 94; then draw a quick-rise on the cam with a  $1\frac{1}{2}$ -inch radius. As the screw will be severed from the bar at  $97\frac{1}{4}$  hundredths, this is the finishing point of the lobe for placing the screw in the slotting bushing. Next construct the quick-drop on the cam and draw another circle *D*,  $\frac{1}{16}$  inch below the largest diameter of the cam, so that the arm will drop back from the chuck before it begins to rise.

Now, to determine the position of the transferring roll, draw two circles *E* and *F* of such diameters that the distance *G* equals the relative distance between the center of the transferring arm lever and the path of the center of the advancing lever; these levers swing through arcs in planes at right angles to each other.

To obtain the center of the transferring lever, relative to the path of the advancing lever, draw a line through the center of the circle *D* and tangent to the circle *F*. Then draw another line tangent to the circle *E* and parallel to the line which is tangent to the circle *F* and passes through the center of the circle *D*. The point where the last drawn line cuts the circle *A* will be the center of the transferring lever. With this point as center and the compasses set to the radius of the transferring lever, strike an arc, and with its center on this arc draw the transferring roll circle *H*, touching the smallest diameter of the cam. The quick-rise on the transferring cam is then constructed, and the finishing point of this rise is made with a  $\frac{1}{4}$ -inch radius, so that the speed at which the arm is traveling will be decreased as it approaches the top of its travel. If this is not done, the arm will hit the stop and rebound, which will have a tendency to knock the screw out of the slotting bushing. When the transferring roll is on the highest point of the cam, the advancing roll should be at the bottom. A clearance of






Fig. 13. Screw-slottting Attachment for the No. 0 Brown & Sharpe Automatic Screw Machine

cam, so that all sizes of screws within the range of the machine can be slotted with this same set of cams.

#### Screw-slotting Attachment for the No. 0 and No. 2 Machines

The principle on which the screw-slotting attachment for the No. 0 and No. 2 machines works does not vary from that used on the No. 00




Fig. 14. Diagram used in laying out Transferring and Advancing Cams for the No. 0 Brown & Sharpe Automatic Screw Machine

machine, but the advancing and transferring cams are located differently. On the No. 00 machine, these cams are held side by side on the front cam-shaft, while in the No. 0 and No. 2 machines, the advancing cam is held on the stud which holds the lead cam, while the transferring cam is held on the front cam-shaft. The movement of the levers,

of course, in this case differs from that on the No. 00 machine. Referring to the illustration Fig. 13, which shows the attachment used on the No. 0 machine, *A* is the advancing cam and *B* the advancing cam lever; *C* is the transferring cam, and *D* the transferring lever. The method of carrying the screw to the saw is similar to that on the No. 00 machine, as are also the other movements, so that this will not need further description. It is, however, necessary to describe the method of laying out the transferring and advancing cams.

The method of laying out the transferring and advancing cams is illustrated diagrammatically in Fig. 14 where the advancing and transferring levers, as well as the cams, are shown in the same plane. The method of finding the starting and finishing points of the lobes on the transferring and advancing cams is the same as that used for the ordinary cross-slide and lead cams. The only point to remember is to retain the proper distances between the centers of the levers, and to swing them into their proper positions. A templet could be made for these cams, which would simplify the problem of laying out the starting and finishing points. When a templet is not available, the method previously described for the No. 00 machine can be used; that is, keeping the center distances in the same relation, in their respective paths, and swinging the rolls into the desired position.

The screw-slotting attachment for the No. 2 Brown & Sharpe automatic screw machine does not differ from that for the No. 0 machine. The transferring cams in both these machines are made in two pieces, as it would be impossible otherwise to assemble them on the front camshaft. As there are no intermediate points at which the transferring arm is to dwell between the chuck and slotting saw, there are no calculations necessary for determining different heights on the transferring cam, the rise from the lowest to the highest point of the cam being sufficient to lift the screw from the chuck to the slotting saw.

The diagram shown in Fig. 11 should be laid out so that all the dimensions required for laying out the height of the lobes on the cams can be found. It is always advisable to allow at least one-hundredth of the cam surface for clearance, between the starting or finishing points of the lobes on the transferring or advancing cams. This allows the transferring arm to stop for a brief interval before the direction of its motion is changed.

## APPENDIX

### MILLING SCREW MACHINE CAMS

There are several methods used for finishing plate cams. Most methods require that the outline be accurately laid out, after which the stock is removed, generally by drilling a series of holes around the outline and breaking away the outer part. The cam is then finished to the scribed lines by milling and filing. This method, however, is slow, and the highest accuracy is not obtainable in this way.

Another method which is applicable to all cams with a constant rise is illustrated and described in the following: A diagrammatical view of the relative positions of the compound vertical milling attachment and the index head used in this method, is shown in Fig. 15. By this method constant-rise cams may be milled, so to speak, automatically, by placing the cam blank on the index head spindle, and gearing the head for spiral milling. An end-mill is held in the compound vertical milling attachment, which is adjustable to any angle in the vertical plane, as indicated. The milling attachment and the spiral head are set at a certain angle with the table surface, this angle being determined by the rise of the cam and the forward feed of the milling machine table for one turn of the index head spindle; this forward feed is usually called the spiral lead for which the machine is geared. It will be clear even to persons unfamiliar with this method, that when the table is feeding forward, the slowly revolving cam blank is fed against the cutting edge of the end-mill, and as this latter is stationary, the radius of the cam will be constantly decreased. It is the object of this article to describe a method for finding the angle to which the spiral head is to be set, and the lead for which the spiral head is to be geared, so as to obtain very accurate results when milling constant-rise cams. The formulas given below and the accompanying tables of leads obtainable on the Brown & Sharpe milling machines, and their logarithms, are used for facilitating the necessary calculations. In order to carry out the calculations by the method outlined, a table of logarithms of numbers (MACHINERY'S Reference Book No. 53) and a table of logarithms of angular functions (MACHINERY'S Reference Book No. 55) are required. In order to find the gears to be used for any spiral lead obtainable on the machine, a book entitled "Tables of Leads for Use with Universal Milling Machines," published by the Brown & Sharpe Mfg. Co., Providence, R. I., should be used.

#### General Formulas for the Calculations

In the following formulas let

$l$  = lead of the cam lobe to be milled; the lead of the cam lobe is the rise of the cam if the given rate of rise were continued for one whole revolution or 360 degrees



$R$  = rise of the cam in a given part  $N$  of the circumference,  
 $N$  = the part of the circumference in which a given rise takes place;  
 $N$  is expressed as a decimal in hundredth of the cam circumference,  
 $L$  = spiral lead for which the milling machine is geared,  
 $a$  = angle to which the index head and milling attachment are to be set.

The finding of the angle  $a$  to which the index head is to be set for any specific case is most easily explained by reference to Fig. 16. In the right-angle triangle shown, the hypotenuse  $L$  represents the distance that the milling machine table will be fed forward while the




Fig. 16. Diagrammatical View showing Method of Milling Cams on the Milling Machine

index head spindle makes one complete revolution, or, in other words,  $L$  is the spiral lead for which the machine is geared. The side  $l$  in the triangle represents the rise that the cam to be milled would have in 360 degrees, or in one complete revolution; hence, this side represents the lead of the cam. It is then clear that

$$\sin a = \frac{l}{L} \quad (1)$$

$$\text{But } l = \frac{R}{N}, \text{ hence: } \sin a = \frac{R}{N \times L} \quad (2)$$

It is apparent from Formula (2) that when  $R$ ,  $N$  and  $L$  are known angle  $a$  can be determined. As it is not practicable, however, to set either the index head or the vertical milling attachment closer than to whole or half degrees, the lead  $L$  must be so selected that the angle

$\alpha$  will be within 5 minutes either way of a whole or a half degree. Hence trial calculations must be made, and it is for the purpose of facilitating these calculations that the tables on pages 36 to 38 have been prepared.

#### Practical Use of Tables and Formulas

The practical use of the formulas given and of the tables can be best explained by means of an example. Assume that a set of cams is designed and drawn as shown in Fig. 17, and that the toolmaker is to be given the necessary data for milling the lobes on these cams. The milling is to be done according to the method illustrated in Fig. 15. The calculations should be made by the draftsman or whoever designs the cams, and it is recommended that the results of the calculations




Fig. 16. Relation between Setting Angle of Index Head, Spiral Lead and Lead of Cam Lobe

be tabulated as shown in the table. Referring to the cam drawings in Fig. 17, let us first take the first lobe on the front-slide cam. Here the rise  $R = 0.155$  inch and this rise takes place in 0.24 of the whole cam circumference. Hence  $N = 0.24$ . We have further:

$$l = \frac{R}{N} = \frac{0.155}{0.24} = 0.6458$$

and, from Formula (1):

$$\sin \alpha = \frac{l}{L} = \frac{0.6458}{L} \quad (3)$$

As already mentioned we must now find a lead  $L$  so selected that angle  $\alpha$  will be within 5 minutes either way of a whole or half degree. In order to accomplish this result proceed as follows:

First find the logarithm of 0.6458:

$$\log 0.6458 = \bar{1}.81010$$

Now turn to the accompanying tables on pages 36 to 38 (Tables XI to XII). Beginning with any lead  $L$  that is larger than the numerator 0.6458, subtract the logarithms of the leads, as found in the tables, from the logarithm of the numerator 0.6458 until, by repeated trials,



TABLE XI. DATA FOR MILLING SCREW MACHINE CAMS

Spiral Lead	Logarithm	Spiral Lead	Logarithm	Spiral Lead	Logarithm	Spiral Lead	Logarithm	Spiral Lead	Logarithm
0.900	1.95424	1.776	0.24944	2.388	0.36791	2.894	0.46150	3.429	0.53517
0.920	1.96648	1.778	0.24998	2.388	0.36884	2.909	0.46374	3.438	0.53681
0.933	1.96988	1.786	0.25188	2.344	0.36996	2.917	0.46494	3.438	0.54258
1.029	0.01242	1.800	0.25527	2.368	0.37438	2.924	0.46598	3.491	0.54295
1.042	0.01787	1.809	0.25744	2.381	0.37676	2.933	0.46731	3.492	0.54307
1.047	0.01995	1.818	0.25959	2.386	0.37767	2.934	0.46746	3.500	0.54407
1.050	0.02119	1.823	0.26079	2.392	0.37876	2.946	0.46923	3.520	0.54654
1.047	0.02316	1.860	0.26951	2.400	0.38021	2.950	0.46982	3.535	0.54889
1.035	0.02548	1.861	0.26975	2.424	0.38453	2.977	0.47378	3.552	0.55047
1.113	0.04766	1.867	0.27114	2.431	0.38578	2.984	0.47480	3.556	0.55096
1.196	0.07778	1.875	0.27300	2.442	0.38775	3.000	0.47712	3.564	0.55194
1.200	0.07918	1.886	0.27554	2.445	0.38823	3.030	0.48144	3.565	0.55206
1.221	0.08672	1.905	0.27969	2.450	0.38917	3.044	0.48344	3.571	0.55279
1.228	0.08920	1.919	0.28307	2.456	0.39023	3.055	0.48501	3.572	0.55291
1.240	0.09342	1.920	0.28330	2.481	0.39463	3.056	0.48515	3.582	0.55418
1.244	0.09482	1.925	0.28443	2.489	0.39603	3.070	0.48714	3.588	0.55485
1.250	0.09691	1.944	0.28870	2.500	0.39794	3.080	0.48855	3.600	0.55630
1.302	0.11461	1.954	0.29092	2.514	0.40037	3.096	0.48940	3.618	0.55847
1.309	0.11694	1.956	0.29137	2.523	0.40346	3.101	0.49150	3.636	0.56062
1.333	0.12458	1.990	0.29885	2.537	0.40483	3.111	0.49290	3.637	0.56074
1.340	0.12710	1.998	0.29950	2.546	0.40586	3.117	0.49374	3.646	0.56182
1.371	0.13704	2.000	0.30108	2.558	0.40790	3.125	0.49485	3.655	0.56259
1.395	0.14457	2.009	0.30298	2.567	0.40943	3.126	0.49499	3.657	0.56312
1.400	0.14618	2.030	0.30750	2.571	0.41010	3.140	0.49693	3.668	0.56684
1.429	0.15508	2.035	0.30856	2.593	0.41380	3.143	0.49734	3.667	0.56481
1.438	0.15625	2.036	0.30878	2.605	0.41581	3.150	0.49831	3.673	0.56502
1.440	0.15836	2.045	0.31089	2.618	0.41797	3.175	0.50174	3.684	0.56632
1.447	0.16047	2.047	0.31112	2.619	0.41814	3.182	0.50270	3.686	0.56656
1.458	0.16376	2.057	0.31323	2.625	0.41913	3.189	0.50365	3.704	0.56867
1.467	0.16643	2.067	0.31534	2.640	0.42160	3.190	0.50379	3.721	0.57066
1.488	0.17280	2.068	0.31669	2.658	0.42455	3.198	0.50488	3.738	0.57206
1.500	0.17609	2.084	0.31890	2.667	0.42603	3.200	0.50515	3.750	0.57408
1.522	0.18241	2.098	0.32077	2.674	0.42716	3.214	0.50705	3.768	0.57558
1.527	0.18384	2.100	0.32222	2.678	0.42781	3.225	0.50853	3.771	0.57646
1.550	0.19033	2.121	0.32654	2.679	0.42797	3.241	0.51068	3.772	0.57657
1.556	0.19201	2.133	0.32899	2.700	0.43136	3.256	0.51263	3.799	0.57967
1.568	0.19396	2.143	0.33102	2.713	0.43345	3.267	0.51415	3.809	0.58061
1.595	0.20276	2.171	0.33666	2.727	0.43569	3.273	0.51495	3.810	0.58092
1.600	0.20412	2.178	0.33806	2.743	0.43823	3.275	0.51521	3.818	0.58184
1.607	0.20602	2.183	0.33885	2.750	0.43933	3.281	0.51601	3.819	0.58195
1.638	0.21165	2.198	0.34005	2.778	0.44378	3.300	0.51851	3.822	0.58229
1.637	0.21405	2.198	0.34104	2.791	0.44576	3.308	0.51957	3.837	0.58399
1.650	0.21748	2.200	0.34242	2.800	0.44716	3.333	0.52284	3.840	0.58433
1.667	0.22194	2.223	0.34674	2.812	0.44902	3.345	0.52440	3.850	0.58546
1.674	0.22376	2.233	0.34869	2.828	0.45148	3.349	0.52492	3.876	0.58838
1.680	0.22531	2.238	0.34966	2.843	0.45378	3.360	0.52634	3.889	0.58984
1.706	0.23198	2.240	0.35025	2.845	0.45408	3.383	0.52930	3.896	0.59062
1.711	0.23325	2.250	0.35218	2.849	0.45469	3.408	0.53186	3.907	0.59134
1.714	0.23401	2.274	0.35679	2.857	0.45591	3.409	0.53268	3.911	0.59229
1.744	0.24155	2.288	0.35908	2.865	0.45712	3.411	0.53268	3.920	0.59329
1.745	0.24180	2.292	0.36021	2.867	0.45743	3.422	0.53428	3.927	0.59406
1.750	0.24304	2.326	0.36661	2.880	0.45939	3.428	0.53504	3.929	0.59428

TABLE XII. DATA FOR MILLING SCREW MACHINE CAMS

Spiral Lead	Logarithm	Spiral Lead	Logarithm	Spiral Lead	Logarithm	Spiral Lead	Logarithm	Spiral Lead	Logarithm
3.977	0.59956	4.573	0.66011	5.160	0.71265	5.848	0.76701	6.548	0.81611
3.979	0.59977	4.583	0.66106	5.168	0.71333	5.861	0.76797	6.568	0.81710
3.987	0.60065	4.588	0.66115	5.185	0.71475	5.867	0.76843	6.578	0.81809
4.000	0.60206	4.584	0.66124	5.186	0.71488	5.898	0.77084	6.600	0.81954
4.011	0.60325	4.651	0.66755	5.195	0.71559	5.913	0.77178	6.645	0.82349
4.019	0.60412	4.655	0.66792	5.209	0.71675	5.920	0.77232	6.667	0.82693
4.040	0.60638	4.667	0.66904	5.210	0.71684	5.926	0.77276	6.689	0.82936
4.059	0.60849	4.675	0.66978	5.226	0.71817	5.933	0.77466	6.697	0.83588
4.060	0.60858	4.687	0.67069	5.233	0.71875	5.954	0.77481	6.698	0.83595
4.070	0.60959	4.688	0.67099	5.236	0.71900	5.969	0.77590	6.719	0.83790
4.078	0.60991	4.691	0.67127	5.238	0.71917	5.973	0.77613	6.720	0.83787
4.074	0.61002	4.714	0.67339	5.250	0.72016	5.980	0.77670	6.735	0.83834
4.091	0.61188	4.786	0.67541	5.266	0.72066	6.000	0.77815	6.750	0.83980
4.093	0.61204	4.782	0.67779	5.280	0.72263	6.016	0.77931	6.757	0.83975
4.114	0.61426	4.778	0.67879	5.288	0.72452	6.090	0.77960	6.766	0.84033
4.125	0.61548	4.778	0.67925	5.316	0.72558	6.661	0.78254	6.784	0.84149
4.185	0.61648	4.784	0.67979	5.323	0.72656	6.077	0.78369	6.806	0.83399
4.144	0.61743	4.785	0.67968	5.333	0.72697	6.069	0.78455	6.818	0.83366
4.167	0.61982	4.800	0.68124	5.347	0.72811	6.109	0.78597	6.823	0.83391
4.186	0.62180	4.813	0.68242	5.348	0.72819	6.113	0.78618	6.825	0.83410
4.200	0.62325	4.821	0.68314	5.357	0.72892	6.122	0.78689	6.857	0.83613
4.242	0.62757	4.849	0.68565	5.358	0.72900	6.125	0.78711	6.875	0.83727
4.258	0.62870	4.861	0.68673	5.375	0.73068	6.137	0.78796	6.880	0.83759
4.264	0.62963	4.884	0.68978	5.400	0.73239	6.140	0.78817	6.944	0.84161
4.267	0.63012	4.889	0.68923	5.413	0.73344	6.143	0.78838	6.945	0.84167
4.278	0.63124	4.896	0.69002	5.426	0.73443	6.160	0.78958	6.963	0.84311
4.286	0.63205	4.900	0.69020	5.427	0.73456	6.171	0.79036	6.977	0.84367
4.300	0.63347	4.911	0.69117	5.444	0.73592	6.173	0.79048	6.983	0.84396
4.320	0.63548	4.914	0.69144	5.455	0.73679	6.202	0.79253	6.984	0.84410
4.341	0.63759	4.950	0.69461	5.469	0.73791	6.222	0.79398	7.000	0.84510
4.342	0.63769	4.961	0.69557	5.473	0.73823	6.234	0.79477	7.018	0.84590
4.361	0.63959	4.978	0.69705	5.496	0.73926	6.250	0.79568	7.040	0.84737
4.368	0.63979	4.984	0.69758	5.500	0.74006	6.255	0.79623	7.071	0.84948
4.364	0.63988	5.000	0.69897	5.556	0.74476	6.279	0.79789	7.104	0.85150
4.365	0.63998	5.017	0.70044	5.568	0.74570	6.286	0.79867	7.106	0.85168
4.375	0.64098	5.023	0.70096	5.581	0.74671	6.300	0.79984	7.111	0.85198
4.386	0.64207	5.029	0.70148	5.583	0.74679	6.343	0.80229	7.130	0.85309
4.400	0.64345	5.040	0.70243	5.600	0.74819	6.350	0.80277	7.143	0.85333
4.444	0.64777	5.074	0.70535	5.625	0.75013	6.364	0.80373	7.159	0.85435
4.465	0.64963	5.080	0.70666	5.657	0.75259	6.379	0.80475	7.163	0.85509
4.466	0.64992	5.088	0.70655	5.696	0.75573	6.396	0.80591	7.167	0.85534
4.477	0.65099	5.091	0.70680	5.714	0.75694	6.400	0.80618	7.176	0.85558
4.479	0.65118	5.093	0.70697	5.730	0.75815	6.417	0.80733	7.200	0.85733
4.480	0.65128	5.105	0.70800	5.733	0.75836	6.439	0.80814	7.268	0.86141
4.500	0.65321	5.116	0.70898	5.756	0.76013	6.450	0.80956	7.272	0.86165
4.522	0.65533	5.119	0.70919	5.759	0.76035	6.460	0.81023	7.273	0.86171
4.537	0.65677	5.120	0.70927	5.760	0.76043	6.465	0.81057	7.292	0.86235
4.545	0.65758	5.138	0.71087	5.788	0.76253	6.482	0.81171	7.310	0.86392
4.546	0.65768	5.134	0.71046	5.814	0.76448	6.512	0.81371	7.314	0.86415
4.548	0.65782	5.142	0.71118	5.818	0.76477	6.515	0.81391	7.326	0.86497
4.553	0.65877	5.143	0.71123	5.838	0.76539	6.534	0.81518	7.330	0.86510
4.567	0.65963	5.156	0.71231	5.847	0.76698	6.545	0.81591	7.333	0.86528

TABLE XIII. DATA FOR MILLING SCREW MACHINE CAMS

Spiral Lead	Logarithm	Spiral Lead	Logarithm	Spiral Lead	Logarithm	Spiral Lead	Logarithm	Spiral Lead	Logarithm
7.384	0.86584	8.061	0.90747	8.958	0.95197	9.828	0.99247	10.800	1.03842
7.347	0.86511	8.103	0.90859	8.959	0.95226	9.844	0.99317	10.858	1.03855
7.371	0.86753	8.119	0.90950	8.980	0.95341	9.900	0.99564	10.859	1.03879
7.373	0.86759	8.140	0.91062	8.980	0.95338	9.921	0.99656	10.909	1.03778
7.400	0.86923	8.145	0.91089	9.000	0.95424	9.933	0.99664	10.913	1.03794
7.408	0.86970	8.148	0.91105	9.044	0.95636	9.943	0.99752	10.987	1.03890
7.424	0.87064	8.149	0.91110	9.074	0.95730	9.954	0.99800	10.945	1.03922
7.443	0.87199	8.163	0.91183	9.091	0.95861	9.997	0.99856	10.949	1.03937
7.465	0.87303	8.167	0.91206	9.115	0.95976	9.968	0.99861	10.972	1.04029
7.467	0.87315	8.182	0.91236	9.134	0.96096	10.000	1.00000	11.000	1.04139
7.500	0.87506	8.186	0.91307	9.137	0.96080	10.038	1.00143	11.021	1.04222
7.525	0.87651	8.213	0.91445	9.148	0.96109	10.046	1.00199	11.057	1.04364
7.543	0.87754	8.229	0.91535	9.164	0.96209	10.057	1.00247	11.111	1.04575
7.576	0.87944	8.250	0.91645	9.167	0.96233	10.078	1.00337	11.137	1.04677
7.597	0.88064	8.306	0.91939	9.210	0.96428	10.080	1.00346	11.160	1.04766
7.601	0.88087	8.312	0.91971	9.214	0.96445	10.101	1.00436	11.163	1.04778
7.611	0.88144	8.333	0.92080	9.260	0.96661	10.159	1.00685	11.169	1.04801
7.619	0.88190	8.324	0.92085	9.302	0.96858	10.175	1.00753	11.198	1.04914
7.620	0.88196	8.381	0.92328	9.308	0.96863	10.139	1.00738	11.200	1.04922
7.636	0.88237	8.373	0.92338	9.333	0.97002	10.136	1.00600	11.225	1.05019
7.639	0.88304	8.377	0.92309	9.334	0.97007	10.209	1.00898	11.250	1.05115
7.644	0.88333	8.400	0.92423	9.351	0.97036	10.228	1.00979	11.313	1.05358
7.657	0.88406	8.437	0.92619	9.375	0.97197	10.238	1.01000	11.314	1.05362
7.674	0.88502	8.457	0.92723	9.383	0.97230	10.238	1.01022	11.363	1.05549
7.675	0.88508	8.494	0.92860	9.385	0.97243	10.267	1.01144	11.401	1.05694
7.679	0.88530	8.435	0.92865	9.406	0.97340	10.236	1.01125	11.429	1.05801
7.680	0.88536	8.506	0.93073	9.423	0.97442	10.312	1.01334	11.454	1.05896
7.700	0.88649	8.523	0.93059	9.439	0.97447	10.313	1.01338	11.459	1.05915
7.714	0.88723	8.527	0.93090	9.460	0.97539	10.320	1.01368	11.467	1.05945
7.732	0.88941	8.532	0.93105	9.473	0.97644	10.336	1.01435	11.512	1.06115
7.778	0.89087	8.534	0.93115	9.524	0.97832	10.370	1.01578	11.513	1.06138
7.792	0.89165	8.552	0.93207	9.545	0.97978	10.371	1.01582	11.520	1.06145
7.812	0.89232	8.556	0.93227	9.546	0.97982	10.390	1.01632	11.574	1.06348
7.815	0.89233	8.572	0.93308	9.547	0.97997	10.417	1.01774	11.629	1.06554
7.818	0.89310	8.594	0.93420	9.549	0.97996	10.419	1.01738	11.638	1.06538
7.838	0.89421	8.600	0.93450	9.556	0.98028	10.451	1.01916	11.637	1.06696
7.855	0.89515	8.640	0.93651	9.569	0.98087	10.467	1.01982	11.638	1.06774
7.857	0.89526	8.631	0.93657	9.593	0.98213	10.473	1.02007	11.695	1.06800
7.872	0.89609	8.632	0.93632	9.600	0.98227	10.476	1.02020	11.719	1.06889
7.875	0.89625	8.637	0.93637	9.625	0.98340	10.477	1.02024	11.721	1.06896
7.888	0.89669	8.721	0.94057	9.643	0.98421	10.500	1.02119	11.728	1.06922
7.920	0.89873	8.737	0.94036	9.675	0.98565	10.558	1.02358	11.733	1.06941
7.936	0.89960	8.730	0.94101	9.690	0.98633	10.571	1.02412	11.757	1.07030
7.954	0.90059	8.750	0.94201	9.697	0.98664	10.606	1.02555	11.785	1.07133
7.955	0.90064	8.772	0.94310	9.723	0.98780	10.631	1.02657	11.786	1.07137
7.963	0.90106	8.800	0.94443	9.741	0.98860	10.655	1.02755	11.825	1.07230
7.974	0.90163	8.833	0.94635	9.763	0.98931	10.659	1.02772	11.852	1.07379
7.994	0.90276	8.839	0.94640	9.773	0.99003	10.667	1.02804	11.905	1.07573
8.000	0.90309	8.839	0.94635	9.778	0.99025	10.694	1.02914	11.938	1.07693
8.021	0.90423	8.909	0.94933	9.796	0.99105	10.713	1.02991	11.944	1.07715
8.035	0.90499	8.929	0.95030	9.813	0.99202	10.714	1.02995	11.960	1.07773
8.038	0.90550	8.930	0.95035	9.823	0.99220	10.750	1.03141	12.000	1.07918

a remainder is obtained which is the logarithm of the sine of an angle which is within 5 minutes of a whole or a half degree. The angle thus found is the setting angle for the index head and the lead giving this angle is the one for which the head is to be geared. Proceeding according to the directions given above we have:

$$\begin{array}{r} \log 0.6458 = \text{I.81010} \\ \text{(Subtract)} \quad \log 0.900 = \text{I.95424} \\ \hline \log \sin \alpha = \text{I.85586} \end{array}$$

From a table of logarithms of sines we find that  $\alpha = 45$  degrees 51 minutes. As this angle is not within 5 minutes of a whole or a half degree, try the next lead in Table XI, as follows:

$$\begin{array}{r} \log 0.6458 = \text{I.81010} \\ \text{(Subtract)} \quad \log 0.930 = \text{I.96848} \\ \hline \log \sin \alpha = \text{I.84162} \end{array}$$

Hence  $\alpha = 43$  degrees 59 minutes.

This angle fills the requirements. No more trials are, therefore, required, and the index head and the compound vertical milling attachment are to be set to 44 degrees; the gears to use for gearing the spiral head for 0.930 inch lead are found from Brown & Sharpe Mfg. Co.'s book "Table of Leads for Use with Universal Milling Machines," as already mentioned.

In using this method, the following conditions must be taken into consideration:

If a spiral lead can be found in the accompanying tables which is exactly equal to the numerator  $l$  in the fraction giving  $\sin \alpha$  in Formula (1), then this lead is the lead for which the spiral head is to be geared. It will be seen, that  $\sin \alpha$  in this case becomes equal to 1, which is the sine of 90 degrees. This indicates that the compound vertical milling attachment and the index head are to be set in a vertical position. The calculations required for this case then become very simple, as no further trials are necessary.

Especial attention should be given to the fact that the spiral leads  $L$  used in the trial calculations must be larger than the numerator  $l$  in the fraction giving  $\sin \alpha$  in Equation (1). If the number expressing the lead were not greater than the numerator, the value of the fraction would be greater than 1, but as the sines of all angles are smaller than 1, this would be an impossible condition.

In finding the lead corresponding to a suitable angle, a simple way is to write the logarithm of the lead  $L$  on the upper edge of a second sheet of paper and to hold this under the originally written value of the logarithm of the numerator  $l$  in Formula (1), putting the difference on the second sheet of paper until a logarithm of  $\sin \alpha$  is found, giving a suitable angle, as explained above. This saves repeating the writing down of the logarithm of the numerator  $l$  for each trial subtraction.

As another example illustrating what has been said, we may calculate the first lobe on the lead cam. Here  $L=0.906$ ,  $N=0.30$ . Hence

$$l = \frac{0.906}{0.30} = 3.02.$$

It is found by repeated trials, starting with  $L=3.03$ , that no lead gives an angle  $a$  even approximately within the given requirements, before we come to the lead 3.111:

$$\begin{aligned} \log 3.02 &= 0.48001 \\ \text{(Subtract)} \quad \log 3.111 &= 0.49290 \\ \hline \log \sin a &= 1.98711 \end{aligned}$$

Hence  $a = 76$  degrees 6 minutes.

TABLE XIV. RESULTS OBTAINED BY THE CALCULATIONS FOR ANGLE AND LEAD

Piece No. 4-817 Computed by H. W. E. Checked by W. W. J. Date: Nov. 17, 1910								
Name of Cam	Rise on Cam in Inches	Number of Hundredths	Angle $a$ in Degrees	Lead in Inches	Gear on Worm	First Gear on Stud	Second Gear on Stud	Gear on Screw
Lead cam	0.906	80	76	8.111	40	72	56	100
Lead cam	0.906	14 $\frac{1}{2}$	80	6.848	100	44	24	86
Front cam	0.155	24	44	0.980	24	72	24	86
Front cam	0.048	18 $\frac{1}{2}$	20	0.980	24	72	24	86
Rear cam	0.837	82 $\frac{1}{2}$	82	1.047	24	64	24	86

While the angle 76 degrees 6 minutes is not quite within the limits that we have specified, it is so nearly so that it is safe enough to assume the setting angle to be 76 degrees, the corresponding lead being 3.111. We can calculate the actual rise of the cam with this lead and angle and compute the error resulting in the rise. From Formula (2) we have:

$$R = \sin a \times N \times L \quad (4)$$

Inserting  $a=76$  degrees,  $N=0.30$ , and  $L=3.111$ , we obtain  $R=0.9056$  inch.

The error in the rise thus is 0.0004 inch, which for all practical purposes can be disregarded. The same method is employed for the other lobes. With a little practice, the work can be carried on rapidly, and the method is very simple to remember.

While it is the best practice always to use a spiral lead which corresponds to an angle within 5 minutes of a whole or half degree, as stated, yet a considerable amount of time may be saved in milling cam lobes with several leads, when the greatest accuracy may not be required, by gearing the machine for the greatest lead of lobe and changing the setting angle of the head for the other leads.



